

# FACILITIES REPAIRS

## *Before and After*

The 90-Day Challenge

# Plumbing

## Boylan Hall, 2<sup>nd</sup> Floor, Men's Bathroom



## Boylan Hall, 3<sup>rd</sup> Floor, Women's Bathroom



## Boylan Hall, 5<sup>th</sup> Floor, Men's Bathroom



## Library, 2<sup>nd</sup> Floor, Men's Bathroom





## Ingersoll Hall, 2<sup>nd</sup> Floor, Women's Bathroom



## Library, Main Lobby





## New Ingersoll, 1<sup>st</sup> Floor, Women's Bathroom



## James Hall, 2<sup>nd</sup> Floor, Women's Bathroom



# Whitehead Hall, 3<sup>rd</sup> Floor, Women's Bathroom

## *Clogged Sink*





## James Hall, 2<sup>nd</sup> Floor, Men's Bathroom



# Electrical



# **West End Building (WEB) Main Floor Computer Lab**

## ***Lights Bulbs Need Replacing***



# **West End Building (WEB) Main Floor Computer Lab**

## ***Light Bulbs Replaced***



## Whitehead Hall, 5<sup>th</sup> Floor, Women's Bathroom



## Boylan Hall, 5<sup>th</sup> Floor, Stairway E, Exit Sign



## Library Café, Scanner Room





# Painting

## Boylan Hall, 4<sup>th</sup> Floor, Stairway C



## Ingersoll Hall, Basement, Stairway C



# Carpentry

# Boylan Hall, 2<sup>nd</sup> Floor, Men's Bathroom

## *Broken Door*





## Library, 2<sup>nd</sup> Floor

